

ERT - Simulacro / ERT - Drill: Run on 29/05/2022

This document was created in MY Compliance Management on 20/09/2022 14:38:52

Audit Details	
Audit name:	ERT - Simulacro / ERT - Drill
Audit date:	29/05/2022
Auditor:	Luis Pinto
Audit details:	Simulacro en áreas de trabajo / Work Area Drill
Overall Outcome:	Completed
Emergencia / Emergency	Emergencias medicas o por lesion / Medical or injury emergencies
Breve descripción del evento / Brief Event Description	28 mayo 2022, PP Ops Primary Crushing, overlands 315-cv-9001/9002 atrapamiento pierna de colaborador May 28, 2022, PP Ops Primary Crushing, overlands 315-cv-9001/9002 collaborator leg entrapment
Especificar ubicación / Specify Location	Primary Crusher overlands 315-cv-9001/9002
Hora de inicio / Starting Time	23:00
Hora de finalización / Ending Time	23:28
Departamento / Department	PP ENG - Primary Crushing

Notes

28 de mayo de 2022, PP Ops Primary Crusher, Colaborador sufre lesion por atrapamiento de pierna en parrilla del piso.

Dentro de las recomendaciones están:

- Visita de familiarización del personal de rescate al área de Trituración Primaria, guiada por el Supervisor de Trituración de Turno (6422 2645), con el objetivo de:
 - Reconocimiento específico de las áreas: Transferencia, Primarias, Screening Plant, etc
 - Reconocimiento de accesos y vías de evacuación de cada circuito.
 - Reconocimiento de Puntos de encuentro o muster points
 - Reconocimiento a vías de accesos parte superior e inferior de cada Trituradora Primaria

May 28, 2022, PP Ops Primary Crusher, Collaborator suffers leg entrapment injury in floor grill.

Among the recommendations are:

- Familiarization visit of the rescue personnel to the Primary Crushing area, guided by the Shift Crushing Supervisor (6422 2645), with the aim of:
Specific recognition of the areas: Transfer, Primary, Screening Plant, etc.

ERT - Simulacro / ERT - Drill: Run on 29/05/2022

This document was created in MY Compliance Management on 20/09/2022 14:38:52

- Recognition of accesses and evacuation routes of each circuit.
- Recognition of meeting points or meeting points
- Acknowledgment of access routes to the top and bottom of each Primary Crusher

Response Summary

Section	Completed	Not completed
Audit	1	0

Audit Criteria

#	Criteria	Details	Response
1	Completed Drill	Responsible will determine the drill	Completed

Signatures

Capacity: supervisor

Name: David Pinto




Documents



traslado a Ambulancia



traslado a Ambulancia



Atención del herido

